Chapter 3.4

List of Contents

1 Codings of the Stepper Motor Control Boards 1

2 Fuses Overview.....2

1 Codings of the Stepper Motor Control Boards

GS IOB-SIN-5Step Boards:
CM+9.9499.8120.3

GS	Designation	Switch	Settings
210	Cassette module 1	JL1	 LJGS210sn2.cdr
		JL 2	 LJGS210sn1.cdr
260	Cassette module 2	JL1	 LJGS260sn2.cdr
		JL2	 LJGS260sn1.cdr
610	5fold-St-Scan Board	JL1	 LJGS610sn2.cdr
		JL2	 LJGS610sn1.cdr

GS IOB-SIN-Step Boards
CM+9.9499.8140.4

202	Rotation Board	JL1	 LJGS202.cdr
412	Postsc-Suct Board	JL1	 LJGS412.cdr
418	Post-Sled Board	JL1	 LJGS418.cdr
428	Pre-Suction Board	JL1	 LJGS428.cdr
434	Prescan-Sled Board	JL1	 LJGS434.cdr
510	Inbuff-Belt Board	JL1	 JLGS510.cdr

GS	Designation	Switch	Settings
532	Inbuff-Door Board	JL1	
552	Outbuff-Push Board	JI1	
556	Outbuff-Roll Board	JL1	

2 Fuses Overview

Board	Fuse	Quality	protects
GS100 MS-Board	SI 1	T 2.5A	GS210, 5 fold stepper motor board cass unit 1
	SI 2	T 2.5A	GS260, 5 fold stepper motor board cass unit 2
	SI 3	T 2.5A	GS610, 5 fold stepper motor board scan unit
	SI 4	T 1A	GS510 Input Buffer Belt board
	SI 5	T 1A	GS532 Input Buffer Door board
	SI 6	T 1A	GS556 Output Buffer Roller board
	SI 7	T 1A	GS552 Output Buffer Push board
	SI 8	T 1A	GS202 Rotation board
	SI 9	T 1A	GS418 Postscan Sled board
	SI 10	T 1A	GS412 Postscan Suction board
	SI 11	T 1A	GS434 Prescan Sled board
	SI 12	T 1A	GS428 Prescan Suction board
	SI 13	T 2.5A	+24 V devices

All fuses are slowblow fuses.